

Machine Protection - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
19366	Feature	Closed	Normal	Provide access to the frequency parameters in the PECL driver	Richard Neswold	03/15/2018 04:01 PM
18173	Feature	Closed	Normal	Detect overflow in averaging registers	Ning Liu	04/04/2018 10:32 AM
16756	Feature	Closed	Normal	Add BASIC CONTROL to V1495's register bank driver.	Richard Neswold	04/13/2018 02:28 PM
12038	Feature	Closed	Normal	After upgrading the firmware, the board should be reset.	Richard Neswold	03/23/2016 03:47 PM